

03500.017615

PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:)	
•	: Examiner: S	S. S. Chen
Takashi FUJIMORI et al.)	
	: Group Art I	Unit: 2852
Application No.: 10/673,502)	
Filed: Sentember 20, 2002	:	
Filed: September 30, 2003)	
For: FIXING APPARATUS	·)	
	;	
U.S. Patent No.: 6,952,541 B2) January 13,	2006
	;	
Issued: October 4, 2005)	
Commission on for Potents		O
Commissioner for Patents		∪ertifi ₍
P.O. Box 1450		IA.

Alexandria, VA 22313-1450

01/17/2006 SZEWDIE1 00000046 6952541 01 FC:1811

CERTIFICATE OF CORRECTION UNDER RULES 322 AND 323

100.00 DP

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and

- Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which
- were not the fault of the Patent and Trademark Office. A Certificate of Correction form is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

Patentees' undersigned attorney may be reached in our Washington, D.C. office by telephone at (202) 530-1010. All correspondence should continue to be directed to our address given below.

Respectfully submitted,

Lawrence A. Sfahl Attorney for Patentees Registration No. 30,110

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3800
Facsimile: (212) 218-2200

LAS/eab

DC_MAIN 227227v1

Staple Here Only!

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.: 6,952,541 B2

DATED: October 4, 2005

INVENTOR(S): Takashi FUJIMORI et al.

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 1:

Line 16, "be" should be deleted.

Line 39, "length wisely" should read -- lengthwise --.

Line 43, "control" should read -- controls --.

COLUMN 2:

Line 49, "raising" should read -- rising --.

Line 63, "continuedly" should read -- continuously --.

COLUMN 5:

Line 43, "after all," should be deleted.

COLUMN 12:

Line 49, "has" should read -- have --.

MAILING ADDRESS OF SENDER:

PATENT NO. 6,952,541 B2

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile
FORM PTO 1050 (REV. 3.82)

No. of add'l. copies @ 30¢ per page

